



INSPECTION REPORT ON EDUCATIONAL INSTITUTION

Roc. No. 107/2019 Dt: 27.07.2019

01. Name and Address of the Education Institution	: Gnanabharati English Medium School, Dabburi St. ICHAPURAM PIN-532312, Srikakulam Dst. AP
02. a) No of Floors	: 03
b) Height in Mtr.	: 10m (approx)
c) Each Floor Height	: GF 10ft; 1 st Floor 10ft; 2 nd Floor 10ft
03. Whether access for the Open space :	
Vehicle is all around is East Provided	: ✓ yes
West	: ✓ yes
North	: ✓ yes
South	: ✓ yes
04. a) Available Fire Extinguishers	: yes
b) Fire Buckets	: 20 Nos
05. Availability Fire Fighting Systems	
a) Hose Reel	: yes
b) Down Comer	: No
c) Yard Hydrant	: No
d) Over Head Tank of 15,000 Ltrs.,	: yes
e) Booster Pumps of 450 LPs	: yes
f) Manual Call Print	:
g) Public Address System	: Available
06. Means of Escape	
a) Average Students per Floor	: 250
b) Total No. of Stair Cases provided	: 6 (Six)
c) Total Width of all Stair Cases	: 10 mtrs
07. Whether Means of Escape is Adequate are not.	: Adequate
08. Whether NOC issued by the Department are Not.	: yes
09. Any Other Remarks	: No


Principal
Gnana Bharati English Medium School
Affiliated to C.B.S.E. Delhi, No-130144
Ichapuram, Dist. Srikakulam (A For) Gnanabharati English Medium School


Secretary/Manager


Signature of the Inspecting Officer
STATION FIRE OFFICER
Andhra Pradesh Fire & Emergency Services Department
Ichapuram, Srikakulam Dist. 532312